HAROLD S. FREDERIC
1269 VAN ZANDT ROAD
CINCINNATI 31, OHIO

REPRESENTATIVE
ESTEY ORGAN CORPORATION
SALES — SERVICE

PIPE ORGAN SERVICE
COURTEOUS, DEPENDABLE, EXPERIENCED

September 30, 1952

Mr. Lewis C. Stiff
Consulting Engineer
Estey Organ Corporation

Dear Mr. Stiff:

Enclosed you will find the drawings for the organ to be installed in the Monfort Heights Community Methodist Church Organ # 3206

One unfortunate item is the poor arrangement for the tone opening. Nothing could be done about either enlarging the opening or extending it upward for a few feet. The curving roof in the church keeps it from going upward.

The blower is to be installed on the same level as the organ, but around the corner as shown in my drawing. There is no other place for it.

The ink lines show the best possible opening for the shades. Hope that connecting both shade frames will not be too much a problem.

If you should need additional information I will be glad to send it on.

Sincerely,

Harold