

M. P. MÖLLER Organ Factory

File

Pipe Organ No. M-9084 Date March 20, 1977
For ST. CLEMENT'S EPISCOPAL CHURCH, EL PASO, TEXAS
Action Electro-Pneumatic Console Present - Detached (1933)
Casing No. Present Finish No Change
Decorations Present Motor Present
Width of Key-bed Present Stop Controls Present
No. Manuals THREE AND PEDAL Wind Pressure Gr., Ch., Ped. 4", Sw. 5"
To be Completed November 20, 1977 Blower Pipe furnished by Purchaser

SPECIFICATIONS

FOR

REPAIRING PRESENT MOLLER ORGAN ^{1933 console?}
Opus ⁺²⁷⁰⁰ 2204-1916, R-495 - 1954

1. Supply new 3'-6" x 3'-6" blower reservoir complete with springs, weights, oval collar for 15" diameter wind conductor and 7' legs. (Installation by others)
2. a. Install five 4 note expression actions, and one 6 note expression action complete with shade jacks and connecting rods.
b. Install three 14" x 16" expression reservoirs complete with the following material:
 - 18 - 3" diameter flanges with gaskets
 - 18 - 3" diameter felted draw bands
 - 4 - 10' lengths 3" diameter wind conductor
 - 1 - 10' lengths 3" diameter flexaust
3. a. Install the following replacement pipes with toeboard/rackboard assemblies as required:

GREAT ORGAN

8	Principal	61 pipes
8	Bourdon	61 pipes
4	Octave	61 pipes
8	Trompette	73-61 pipes

- b. Install four sets of top note pipes.
4. Install the following new pipes and action complete with ^{small Concussion} ~~all necessary wind~~ conductor, 1'-4" x 1'-9" reservoir, switch, wiring, supports, etc.

GREAT ORGAN

III Mixture 183 pipes

5. Install replacement stop keys for above changes.

RVK/mr
5/18/77

Ⓢ 51066
v s

W 2007 Arg Cl of NA
810 N Campbell
74902