

M. P. MÖLLER Organ Factory

Pipe Organ No. R-623 Date July 7, 1958
For ST. MICHAEL'S LUTHERAN CHURCH, HARRISBURG, PA.
Action Electro-Pneumatic Console No Change
Casing No. No Change Finish No Change
Decorations No Change Motor Present - No Change
Width of Key-bed Standard Stop Controls No Change
No. Manuals Two and Pedal Wind Pressure No Change
To be Completed Blower Pipe furnished by Purchaser

SPECIFICATIONS

FOR

REPAIRING AND MOVING PRESENT MOLLER ORGAN OPUS 3047 - 1922

1. Dismantle and pack for truck shipment the present two manual Moller Organ Opus 3047 now installed in St. John's Lutheran Sunday School, Hagerstown, Md.
2. Supply necessary drayage from St. John's Lutheran Church, Hagerstown, Md. to St. Michael's Lutheran Church, Harrisburg, Pa.
3. Make the following repair to the existing organ parts -
 - Recover 7 shade and bumper pneumatics
 - Recover one 10" x 12" shade reservoir (pneumatic type)
 - Install new return springs for shade action
 - Recover nine 73-note unit action switches
 - Recover four 32-note pedal switches
 - Supply and install new tuning slides as follows:

8' Gamba	73 tuners	1 - 73
8' Dulciana	73 tuners	1 - 73
8' Violin Diapason T.C.	61 tuners	13 - 73
8' Voix Celeste T.C.	61 tuners	13 - 73
8' Melodia	12 tuners	62 - 73
 - Repair broken reed pipes
4. The Church to provide and install expression chamber partitions according to drawings supplied by M. P. Moller, Inc. Swell box to be planned for installation to the right facing gallery and using certain existing walls and ceiling as applicable to develop an organ space 10'-6" from side wall to front of swell box and 11'-10" from back wall to end of swell box.
Existing expression shades and action to be used across 11'-0" section toward choir spaces.
5. Present organ cables to be used between organ and console.
Church to provide adequate space or conduits as required for installation.
6. The existing organ Opus 3047 to be installed in the Gallery Organ space prepared and provided by the church according to information supplied by M. P. Moller, Inc.
7. The church to provide and install all electric wiring necessary for the 2 H.P. motor on Kinetic Blower No. L-181, Style 2 JYM, and make any changes or additions required for the galvanized wind conductor between organ, blower and console.