

A-8878

M. P. MÖLLER Organ Factory

2/6

Pipe Organ No.	A-8878	Date	December 7, 1931
For	ST. LUKE'S EPISCOPAL CHURCH, CLEVELAND, TENNESSEE		
Action	Electro-Pneumatic	Console	Present - Detached
Casing No.	None	Finish	No change
Decorations	None	Motor	Present 1 H.P., Style 3-P-2722
Width of Key-bed	Standard	Stop Controls	Tilting Tablets
No. Manuals	TWO AND PEDAL	Wind Pressure	4"
To be Completed	August 1, 1932	Blower Pipe furnished by	Present

SPECIFICATIONS

FOR

CHANGING TONALLY PRESENT
MÖLLER ORGAN OPUS 8878 - 1956 36286

CONSOLE	Replace all stop and coupler controls.
PIPES	Install new pipes as indicated by specifications.
GENERAL	Rewire Pedal 16 Dulciana to 8' Gamba. All pipework to be refinished for best tonal results. All parts of present organ not required to complete this contract are to be removed by and become the property of M.P.Möller, Inc.

SPECIFICATIONS

FOR

ORGAN AND CONSOLE

GREAT ORGAN

ALL UNITS

1	8	Principal.....present pipes and action.....	73 pipes
2	8	Gedeckt.....present pipes and action.....	85 pipes
3	8	Gamba.....present pipes and action.....	61 pipes
4	4	Octavefrom #1.....	61 notes
5	4	Spitz Principal....new pipes; present Dulciana action.....	85 pipes
6	4	Flutefrom #2	61 notes
7	2	Spitz Octave.....from #5	61 notes
8	1-1/3	Quintfrom #5	61 notes
9	1	Zimbelfrom #5	61 notes
10	8	Trompettefrom #20	61 notes

SWELL ORGAN

11	16	Bourdon.....	from #2.....	49 notes
12	8	Gedeckt	from #2.....	61 notes
13	8	Gamba	from #3.....	61 notes
14	8	Celeste	present pipes and action.....	49 pipes
15	4	Spitz Principal....	from #5.....	61 notes
16	4	Flute	from #2.....	61 notes
17	2-2/3	Nazard	from #2.....	61 notes
18	2	Spitz Octave.....	from #5.....	61 notes
19	2	Flute.....	from #2.....	61 notes
20	8	Trompette	new pipes; present 8 Trumpet action.....	73 pipes
21	4	Clairon	from #20.....	61 notes
22		Tremolo		

PEDAL ORGAN

23	16	Bourdon.....	present 12 pipes; 20 from #2.....	32 notes
24	16	Dulciana	present 12 pipes; 20 from #3.....	32 notes
25	8	Principal.....	from #1.....	32 notes
26	8	Gedeckt	from #2.....	32 notes
27	4	Octave.....	from #1.....	32 notes
28	4	Flute	from #2.....	32 notes

COUPLERS - no change

29	Swell to Great
30	Great to Pedal
31	Swell to Pedal

ADJUSTABLE COMBINATIONS - no changePEDAL MOVEMENTS - no changeACCESSORIES - no change

No. A-8878

DATE OF ISSUE December 21, 1981 COMPLETE ON OR BEFORE August 1, 1982

ORDER To E. Benchoff and L. Shrader

Manufacture and ship the following additions for organ #8878, Cleveland, Tenn., according to scale sheets, drawings, orders, etc. to be issued separately.

4' Principal - 85 pipes and action

8' Trompette - 73 pipes and action

and all other materials required to complete the installation.

Forward as directed below. Charge all loading and shipping time to Z-65.

COPIES TO: SHIPPING INSTRUCTIONS.

W.R.Daniels
K.M.Moller
P.M.Daniels
Gillett
Klock
Kreglo
Mrs. Alder
File

To—
St. Luke's Episcopal Church
P. O. Box S
Cleveland, Tennessee 37311

VIA— M. P. Moller, Inc. Truck or Motor Freight
IDENTIFY PL, SHIPPING AND INVOICE BY CUSTOMER'S ORDER NO.

SIGNED *M. Moller*
Order Department

IMPORTANT

Individuals receiving orders are responsible for the return of order to Order Department immediately following completion of specified work. Materials are to be listed on reverse side upon request only. Copies of orders are issued as deemed necessary to various departments and individuals. These are not to be returned.

DATE COMMENCED

DATE COMPLETED

SIGNED _____
Personnel

A 8878

St. Luke's Episcopal Church

Cleveland, Tennessee

GORDON BERNARD
RECTOR

POST OFFICE BOX 5

August 20, 1981

M. P. Möller, Inc.
Hagerstown, MD 21740

Gentlemen:

I am writing to you in regards to some major work which needs to be done to the organ at St. Luke's. Our organ (# 8878) was installed in 1956 and is in need of some major repairs. There has been some damage to some of the pipes, especially the reeds; a couple of the pipes are broken, and the reeds will not stay tuned. The reed tongues seem to be in good shape, but the wedge is out of place in many.

Would it be possible for your company to remove the damaged rank to your factory for revoicing and repair as well as to make the other repairs as needed? We would also like to explore the possibility of adding another 2' rank if there is adequate space.

If a representative of your company will be in our area in the near future, we would appreciate his inspecting the organ to determine what needs to be done and how to go about it. If it is necessary for your representative to make a special trip, our vestry will help to defray the cost of any reasonable expense.

We will appreciate your advice and assistance in this matter.

Sincerely yours,

Fred Wood

Frederick A. Wood
Organist-Choirmaster

Hog A 8878

January 6, 1982

Mr. Harry Mellor
St. Luke's Episcopal Church
P. O. Box 5
Cleveland, Tennessee 37311

Dear Sir:

Enclosed please find the accepted contract for the tonal revisions of the Moller organ at St. Luke's Episcopal Church in Cleveland, Tennessee. These tonal revisions are going to make a tremendous difference in the variety of color and tonal flexibility of this instrument. We thank you for this contract and congratulate you on your vision for making these important additions.

Please note that the contract only includes tonal work and there is no provision for mechanical repairs. On inspection last fall, the organ seemed to be in excellent mechanical condition and no major mechanical problems were evident. However, the company has asked me to call this to your attention so as to avoid misunderstanding should any mechanical problems occur. We do not anticipate any.

We look forward to having the work completed by August 1. We will keep you informed as to our schedule for delivery, installation, and completion. Let us know if you have any questions.

Very truly yours,

William E. Gray, Jr.

WEGJr/am
Encl