

Warren Congregational Church
Warren, Connecticut

Rb. Hook & Hastings, ca. 1890s, factory repair of storm damage and altered

E. & G.G. Hook & Hastings No. 636, 1872

Compasses: 58/27

Pitch and pressure: still A450?, w.p. 67mm (2 5/8")

Mechanical stop action.

GREAT

Op. Diap'n.	C-F# stopt wood, G-f#° zinc, façade; from g° interior, spotted. Repitched ½ step @ g°
Dulciana	C-B Quintadena, then t.c. Dulciana
Octave	C-E zinc, remainder common metal

SWELL [enclosed]

St'd. Diap'n.	II Man.	wood, t.c.; c# ³ -a ³ open flues, common metal; partially ca. 1890
Viola	II. Man.	common metal, t.c; box beards 13-17; softened to become Aeoline
Unison Bass	II. Man.	1-12 wood
Flute	II. Man.	1-5 zinc, then common metal; open cylindrical 4'

PEDAL

Sub Bass Ped.	Stop'd wood 16'
---------------	-----------------

MECHANICALS

I. M. to Pedal
II. M. to Pedal
Manual Coupler
Tremulo
Balanced Swell pedal [ca. 1890s] with new vertical shutters
Foot pumping pedal
Manual pumping lever on right side
Nameboard wind indicator and right-side tell-tale