

M. P. MÖLLER Organ Factory

Pipe Organ No.	M-1660	Date	February 15, 1980
For	FIRST UNITED METHODIST CHURCH, DOTHAN, ALABAMA		
Action	Electro-Pneumatic	Console	Present - Attached
Casing No.	Present	Finish	Present
Decorations	None	Motor	Present .15 HP Style 602
Width of Key-bed	Standard	Stop Controls	Tilting Tablets
No. Manuals	TWO AND PEDAL	Wind Pressure	2-3/4" & 4"
To be Completed	As scheduled	Blower Pipe furnished by	Present

SPECIFICATIONS

FOR

REPAIRING PRESENT 70-2 ORGAN
OPUS 11275 - 1978 *Fire damage*

CONSOLE	Replace manual keys, contacts, and contact mains. Clean, buff and re-ink all tilting tablets. Clean and polish pedal keyboard and bench.
CHESTS	Releather and refinish 18 note pedal chest.
PIPES	Rework miter joints on wood pipes. Wash and dip metal pipes. Check pipes on voicing machine.
ORGAN CASE	Replace one door.
GENERAL	Wash all organ and cabinet parts with warm water and solvent. Refinish any and all parts as needed to return to original appearance. Install all action and pipes and tune and tone regulate.